

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2017

Submitted Date:

06/07/2017

Document Number:

679902631

FIELD INSPECTION FORM

Loc ID 321711 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77269

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207831	WELL	PR	08/11/1989	WA	017-06766	FRONTERA 24-13 18	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	American 228		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 207831 Type: WELL API Number: 017-06766 Status: PR Insp. Status: PR

Producing Well

Comment: Well is SI at time of inspection. Central tank battery for (Frontera Unit 13, 14, 15, 16, 17, 18, 19, 20) 3100' E @ 38.741730/-102.054260

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT