

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401302441
Date Received:
06/07/2017

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
1 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705
Name of Operator: WPX ENERGY PRODUCTION LLC
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Lacey Granillo	505-333-1816	lacey.granillo@wpxenergy.com
Deborah Watson	505-333-1880	deborah.watson@wpxenergy.com
Darren Rowley	505-947-4974	darren.rowley@wpxenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601589
Inspection Date: 06/02/2017 FIR Submit Date: 06/02/2017 FIR Status:

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC Company Number: 96705
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 325146

Location Name: BONDAD 33-9-N33N9W Number: 14SWNW County: LA PLATA
Qtrqr: SWN Sec: 14 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.106579 Longitude: -107.801306

FACILITY - API Number: 05-067-00 Facility ID: 214121

Facility Name: BONDAD 33-9 Number: 1
Qtrqr: SWN Sec: 14 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.106579 Longitude: -107.801306

CORRECTIVE ACTIONS:

1 CA# 79376

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the Phase II of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all riser Risers/ Flowlines/ Pipelines .

Date: 06/30/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: Regarding the risers identified in photos 2 and 3, these appear to be pipeline pipe to soil cathodic protection testing ports that according to pipeline markers belong to BP. Please contact the operator at the phone number listed on the pipeline marker. (See attached photos)
Regarding the risers identified in photo 6, these appear to be pipeline tracer wires used to located the pipeline. According to the nearby pipeline marker the tracer wires belong Elmridge. Please contact the operator at the number listed on the pipeline marker. (See attached photo).
WPX Energy would be happy to discuss any question regarding site conditons or to meet with you on location for further clarification.

COGCC Decision: Approved

COGCC Representative:

2 CA# 79377

Corrective Action: Control weeds.

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 06/06/2017

Operator Comment: Noxious weeds were sprayed on June 6. Spraying for noxious weeds at the site is consistent with WPX Energy's noxious weed policy: noxious weeds at the site will be sprayed again Fall 2017 and Spring 2018. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deborah Watson

Signed: _____

Title: Environmental Specialist

Date: 6/7/2017 10:49:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401302441	FIR RESOLUTION SUBMITTED
401302463	pipeline tracer wire
401302467	pipeline pipe to soil test port #1
401302536	pipeline pipe to soil test port #2
401302539	location sprayed for noxious weeds
401302545	location sprayed for noxious weeds

Total Attach: 6 Files