



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 3. View of the western cut-slope approximately 15-20 feet high from the southwestern edge facing northward.



Photo 4. View of musk thistles (*Carduus nutans*) in the project area.



Photo 5. View of spotted knapweed (*Centaurea maculosa*) rosettes within the project area .



Photo 6. Another view of spotted knapweed rosettes within the project area.



Photo 7. View of pipeline riser remaining within the project area at 37.11712 latitude and -108.14414 longitude.



Photo 8. View of culvert still present along the access road near the entrance to the well pad.