

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2017

Submitted Date:

06/12/2017

Document Number:

679902638

**FIELD INSPECTION FORM**

Loc ID 314194 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #210  
City: AURORA State: CO Zip: 80016

**Findings:**

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725	ed@renegadeoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227897	WELL	PR	12/30/1983	GW	099-06224	IDLER E 2	PR

**General Comment:**

<b>Location</b>					
<b>Lease Road:</b>					
Type	Main				
comment:	Gravel county road. Access wellhead through alfalfa patch				
Corrective ActionL				Date:	
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Sticker on tank				
Corrective Action:				Date:	
Type	OTHER				
Comment:	Lease sign by meter shed				
Corrective Action:				Date:	
Type	WELLHEAD				
Comment:	Lease sign by wellhead				
Corrective Action:				Date:	
<b>Emergency Contact Number:</b>					
Comment:					
Corrective Action:				Date:	_____
<b>Good Housekeeping:</b>					
Type	WEEDS				
Comment:	Maintain weeds between HGS and water tank. Remove dead weeds around water tank and maintain weeds in fence				
Corrective Action:				Date:	
Overall Good: <input checked="" type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	SEPARATOR				
Comment:	Wire fence around meter shed and HGS				
Corrective Action:				Date:	
Type	TANK BATTERY				
Comment:	Wire fence around water tank				
Corrective Action:				Date:	
Type	WELLHEAD				
Comment:	Pipe fence around wellhead				
Corrective Action:				Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment: Meter run on west side of CR 2			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment: HGS on west side of meter shed			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment: Bird protector on HGS fire tube			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		38.088750,-102.723980
Comment: Metal stock tank 150' west of CR 2					
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 227897 Type: WELL API Number: 099-06224 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Meter shed is 930' NE of wellhead](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: [Location is farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT