

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No		
Comment:	<input style="width: 95%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	TANK BATTERY		
Comment:	Wire fence around tank battery		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 227737 Type: WELL API Number: 099-06063 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT