

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2017

Submitted Date:

06/13/2017

Document Number:

679902644**FIELD INSPECTION FORM**
 Loc ID 321173 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 76175Name of Operator: SANDLIN OIL CORPAddress: 621 17TH STCity: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Sandlin, Gary		SandlinOilCorporation@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259738	WELL	PR	03/29/2001	GW	009-06617	HEIRONIMUS 1	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access to wellhead is farmed over		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by VGS		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on south side of wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed is 1800' SW of wellhead		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Parkersburg unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.181830,-102.126820	
Comment: Tank is empty at time of inspection and stored neatly on location						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	150bbbs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms around entire location					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	259738	Type:	WELL	API Number:	009-06617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central meter run for (Heironymous 1 & Leach 1) 1800' SW								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT