

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2017

Submitted Date:

06/14/2017

Document Number:

680302010**FIELD INSPECTION FORM**

Loc ID 304663 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 75027Name of Operator: ROSEWOOD RESOURCES INCAddress: 2101 CEDAR SPRINGS RD STE 1500City: DALLAS State: TX Zip: 75201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Krehmeyer, James	970-848-2228	jkrehmeyer@rosewd.com	Cell # 970-630-3880

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270448	WELL	PR	02/20/2004	GW	125-08833	MCCONNELL 1-12	PR

**General Comment:**Routine Site Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Located within irrigated cropland		
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 0		
Comment:	Flowing		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>		
Type		

Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 270448	Type: WELL	API Number: 125-08833	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Flowing GW			
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: Located within irrigated cropland w/annual tillage

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT