



Photo 1: View of well head and debris facing northward.



Photo 2: View of the project area from the northwestern corner facing center. Junk and debris are stored on location. Location is infested with thousands of Russian knapweed (*Acroptilon repens*).