

Inspection Photos

6/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 318062

Inspection Doc. Number: 682502253

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120
Location ID: 318062



Photo 1: Photo taken from the north end of the well location, facing south. Photo shows reclamation along the well in process.



Photo 2: Photo taken from the west end of the well location. Photo shows scotch thistle on location.