

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/09/2017

Submitted Date:

06/09/2017

Document Number:

674005342**FIELD INSPECTION FORM**

Loc ID 418316 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	
Pesicka, Conor		conor.pesicka@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418321	WELL	SI	03/01/2017	OW	123-31899	NCLP "USX AA 05-08	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: <u>06/20/2017</u>

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Bard Wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:	GPS of southeast corner: 40.51593, -104.45577		
Corrective Action:			Date:
Type: Flow Line	#		
Comment:	Wellhead: Unable to determine due to weeds. Battery: 2 - 2 Inch Steel Separator Area: 10 - 2 Inch Steel Active 3 - 1 Inch Steel Marked Inactive 5 - 2 Inch Steel in doghouse		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	53 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with crude oil tank.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		40.515560,-104.455830
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 418321 Type: WELL API Number: 123-31899 Status: SI Insp. Status: SI

Complaint

Comment: Complaint number: 200442930
 Sound Complaint, Noise source compressors located southeast of residence.
 Sound survey in attachments. Operations were within allowable limits.
 Further details are included in attachments.

Corrective Action:

Date:

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

BradenHead

Comment: Bradenhead plumbed to surface.

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Inspection conducted in response to complaint number: 200442930	carlilec	06/09/2017
Inspection number: 674005342		
Weeds at wellhead require followup inspection.		
Noise survey indicated the operations were within permitted limits.		
Company representative contacted at compressor facility: Chris Madrid		
See complaint details document in attachments.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305308	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167548
674005343	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167542
674005344	Sound Survey Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167543
674005345	Complaint Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167544