FORM INSP Rev X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

Inspection Date: 06/08/2017
Submitted Date: 06/09/2017
Document Number: 685303264

Loc ID: 320863
Inspector Name: St John, William (Cal)
On-Site Inspection: ☐
2A Doc Num:

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 26625
Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-

Contact Information:

Contact Name	Phone	Email	Comment
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	All Inspections
Archuleta, Amy		aarchuleta@elmridge.net	SW Inspection Reports
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205261	WELL	PR	07/07/2000	GW	007-06140	PARGIN MOUNTAIN UNIT 11	PR

General Comment:

See link at end of report for path to downloadable pictures. Witnessed MIT 06/08/2017.

Inspector Name: St John, William (Cal)

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multilple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,

Comment:			
Corrective Action:		Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	20 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:	Weeds inside containment berms. Corrective action completed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID:	205261	Type:	WELL	API Number:	007-06140	Status:	PR	Insp. Status:	PR

Idle Well

Purpose: [X] Shut In [ ] Temporarily Abandoned Reminder:

Comment: Production records indicate last reported production was July 2014. Inspection status reflects PR but the well production report shows the well has been reported as SI since August 2014. MIT completed to comply with Rule 326.b.

Well was pressured up to initial test pressure of 405 psi. Pressure was stabile and 405 psi was maintained throughout extended 30 minute test period. See attached photo documentation. Operator will submit required Form 21 and chart.

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
401305267	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167504
685303278	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167462
685303279	Tank contianment with weeds removed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167463
685303280	Chart 5 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167464
685303281	Chart 10 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167465
685303282	Chart 20 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167466
685303283	Chart 30 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167467