

Photo#1:
View into Location to North.



Photo#2:
View out from Location to South.



June 8, 2017

Photo#3:

Degraded Silt Fence remains along NE perimeter.



Photo#4:

Gravel/ Material piles remain on Location.



June 8, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Koch PA Warr-Kinnamon API#103-09636