



**photo 1:** Facing north at the location. The crop has not re-established in this area.



**photo 2:** Facing northeast at the location. This area approximately 100'x40' does not have adequate crop cover.





**photo 3:** Facing west at the surrounding crop cover.