

# Inspection Photos

## Location Number: 331768



**Photo 1 Location entrance along HYW 66 from the east. Note culvert and rig signage**



**Photo 2 Location entrance signage from south**



# Inspection Photos



**Photo 3 Trackpad with entrance and exit cattle guards from south west**



**Photo 4 Hay bales along north side from west**



# Inspection Photos



**Photo 5 Covered trash receptacle from the south**



**Photo 6 Traffic plan from overhead**

# Inspection Photos



**Photo 7 Secondary containment for chemicals from the east**



**Photo 8 Curtained and conex chemical storage from the east**



# Inspection Photos



**Photo 8**



**Photo 9**

# Inspection Photos

[illegible]

**Photo 10 Drilling permit from overhead.**

**Photo 11 Haybales and ditch along southern edge from the east**