

Inspection Photos

6/16/2017

Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120

Location ID: 318950

Inspection Doc. Number: 682502273

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120
Location ID: 318950



Photo 1: Photo taken from the battery location, facing east. Photo shows meter shed remaining at battery location.



Photo 2: Photo taken from the west end of the battery location, facing north. Photo shows six pipe risers remaining at battery location.

Inspection Photos

Operator: KERR MCGEE OIL & GAS ONSHORE

LP - 47120

Location ID: 318950



Photo 3: Photo taken from the battery location, facing northwest. Photo shows Scotch thistle. This is a Colorado State listed noxious weed and needs to be managed.



Photo 4: Photo taken from the well location, facing north. Photo shows vegetation over the reclamation area. Vegetation predominantly undesirable weedy species such as *Bromus tectorum*.

Inspection Photos

Operator: KERR MCGEE OIL & GAS ONSHORE

LP - 47120

Location ID: 318950



Photo 5: Photo taken from the well location, facing east. Photo shows vegetation over the reclamation area. Vegetation predominantly undesirable weedy species such as Bromus tectorum.



Photo 6: Photo taken from the well location, facing south. Photo shows vegetation over the reclamation area. Vegetation predominantly undesirable weedy species such as Bromus tectorum..

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120
Location ID: 318950



Photo 7: Photo taken from the well location, facing west. Photo shows vegetation over the reclamation area. Vegetation predominantly undesirable weedy species such as *Bromus tectorum*.