

Inspection Photos

6/16/2017

Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120

Location ID: 319201

Inspection Doc. Number: 682502275
Weld County, CO

Aaron Trujillo
Reclamation Specialist
COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120
Location ID: 319201



Photo 1: Photo taken from the well location. Crop on well location is noticeably stunted when compared to reference.



Photo 2: Photo taken from the battery location. Crop on well location is noticeably stunted when compared to reference. Areas of battery also remain void of crop growth.

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120
Location ID: 319201



Photo 3: Photo taken from the reference area. Photo shows crop growth on the reference. Yellow area shows tank battery location. Crop growth on well and battery location is noticeably stunted when compared to reference.