

Inspection Photos

6/16/2017

Operator: BARRETT CORPORATION* BILL -
10071

Location ID: 318664

Inspection Doc. Number: 682502290

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: BARRETT CORPORATION* BILL - 10071
Location ID: 318664



Photo 1: Photo taken from the south end of the tank battery location, facing north. Per CA from inspection doc. #682502057. Reclamation in process. Site stabilization of the location will need to occur per 1003.b