



**photo 1:** Facing south at the location. The crop does not appear to be uniformly establishing at the location.



**photo 2:** Facing southwest toward the location.





**photo 3:** There is gravel that remains at the location.



**photo 3:** There is a marker which has been ran over at the location.