

Photo#1:
Overview of Location to East.



June 13, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram OP PA Kelley API#077-08884

Photo#2:

View of Subsidence approximately 10ft South of SI Well.

Photo#3:



June 13, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram OP PA Kelley API#077-08884