

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2017

Submitted Date:

06/13/2017

Document Number:

679902645**FIELD INSPECTION FORM**
 Loc ID 321185 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281917	WELL	PR	02/10/2015	GW	009-06635	MAMA BEAR 1-1B	PR

General Comment:[Submit production reports from previous months](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:	Meter shed is 2500' NE of wellhead on SW corner of storage yard			
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:	Bethlehem unit			
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	Gas scrubber			
Corrective Action:		Date:		
Type: Prime Mover	# 1			
Comment:	Arrow gas engine			
Corrective Action:		Date:		
Type: Vertical Separator	# 1			
Comment:	Vertical gas separator on south side of meter shed			
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		37.383010,-102.214190

Comment:	Fiberglass open top water tank w/Adequate wildlife netting. Gray tank on east side of production tank is anchored down and stored on location. This tank is empty and not plumbed into production	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms need maintenance for capacity			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	281917	Type:	WELL	API Number:	009-06635	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Meter shed is 2500' NE of wellhead on SW corner of storage yard								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401307991	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4169866