

# Inspection Photos

6/20/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 318182

Inspection Doc. Number: 682502292

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 318182



**Photo 1:** Photo taken from the well location, facing southeast. Photo shows well is predominantly undesirable weedy plant species, and does not reflect the adjacent perennial cropland.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 318182



**Photo 2:** Photo taken from the east end of the battery location, facing west. Photo shows location remains unvegetated, and without any controls to stabilize the location.



**Photo 3:** Photo taken from the the battery location, facing west. Photo shows Access road remains evident, unvegetated, and without any stabilization controls.



Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 318182



**Photo 4:** Photo taken from the access road, facing east. Photo shows cattle guard has been removed. Photo also shows access road remains evident, unvegetated, and without any stabilization controls.



**Photo 5:** Photo taken from the east end of the battery location. Photo shows water well that feeds water to the irrigation sprinkler pivot to the east.