

Inspection Photos

6/20/2017

Operator: PDC ENERGY INC - 69175

Location ID: 330004

Inspection Doc. Number: 682502298

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 330004



Photo 1: Photo taken from the well location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from the well location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 330004



Photo 3: Photo taken from the well location, facing south. Photo shows vegetation over the reclamation area.



Photo 4: Photo taken from the well location, facing west. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 330004




Photo 5: 2012 aerial imagery. Photo shows well and tank battery. Well was PAd 2015. Photo shows facilities at the battery location.



Photo 6: Current (2016) aerial imagery. Photo shows facilities, except for the two meter sheds, have been removed. Note DCP operates a compressor station to the immediate north end of the PDC Becker 5-1 tank battery.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 330004



Photo 7: Photo taken from the battery location, facing west. Photo shows stakes for active monitoring wells. Active remediation project on battery in process.



Photo 8: Photo taken from the battery location, facing east. Photo shows two (2) meter sheds remaining. These need to be removed per reclamation requirements, and per the May 2, 2017 Flowline/Pipeline/Riser NTO

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 330004




Photo 9: Photo of the inside door of the meter shed.
Becker 5-1 , 15, written on door.



Photo 10: Photo of the inside door of the meter shed.
Becker 5-1 , 15, written on door.