

**Inspection Photos**  
**Location Name: LAMBERT 2**  
**API: 05-001-08491**



**STAINED SOIL SEPERATOR**



**STAINED SOIL AND LEAKING PIPES INSDE SEPERATOR  
HOUSE**