

Inspection Photos
Location Name: LAMBERT 2
API: 05-001-08491



CONTAINER FULL OF PARAFIN



STAINED SOIL AROUND MOTOR MOUNTS