

Flowline and Final Reclamation Inspection

June 21, 2017

Operator: SOVEREIGN OPERATING COMPANY LLC- #10383

API: 05-014-09051

Broomfield County, CO

SESW Section 8 T1S R68W

Chris Binschus

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BROZOVICH #MA 8-14J
API: 05-014-09051



Photo 1. Photo taken from the well location. Operator needs to remove the sign from the location.



Photo 2. Photo taken from the southern tank battery location, facing North. Well and tank battery have not been reclaimed per Rule 1004.

Inspection Photos
Location Name: BROZOVICH #MA 8-14J
API: 05-014-09051



Photo 3. Photo taken from the well location, facing West. Access road has not been regraded and contoured per Rule 1004.



Photo 4. Photo taken from the just west of the meter shed, facing North. Operator needs to remove the cattle guard from location.

Inspection Photos
Location Name: BROZOVICH #MA 8-14J
API: 05-014-09051



Photo 5. Photo taken of the meter shed observed along the eastern tank battery, facing East.



Photo 6. Lat/Long coordinates of the meter shed.

Inspection Photos
Location Name: BROZOVICH #MA 8-14J
API: 05-014-09051



Photo 7. Mush thistle observed throughout the tank battery and well location. This is a List B Colorado Noxious weed that the Operator needs to manage and control.



Photo 8. Diffuse knapweed observed along portions of the tank battery location. This is a List B Colorado Noxious weed that the Operator needs to manage and control.