

Inspection Photos

6/21/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 322641

Inspection Doc. Number: 682502318

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 322641



Photo 1: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.