

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2017

Submitted Date:

06/22/2017

Document Number:

675103687**FIELD INSPECTION FORM**

Loc ID 323978 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| , Encana     |       | cogcc.inspections@encana.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 211395      | WELL | PR     | 12/22/1997  | GW         | 045-07155 | BOULTON 33-10 (J33NE) | EG          |

**General Comment:**2017 Flowline NTO inspection 1000' buffer

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Present/complete     |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Present/complete     |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Present/complete     |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: Present/complete

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |  |       |                 |
|-----------------------------------|--|-------|-----------------|
| <b>Equipment:</b>                 |  |       | corrective date |
| Type: Flow Line                   | #  |       |                 |
| Comment:                          | IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 1" water/oil dump line from separator to tank. 1 – 1" well blow down line from separator to tank. 1-1" water/oil dump line from separator to tank battery. |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Horizontal Heated Separator | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Emission Control Device     | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Plunger Lift                | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Gas Meter Run               | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Bird Protectors             | # 3  |       |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CONDENSATE         | 1 | 300 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 211395 Type: WELL API Number: 045-07155 Status: PR Insp. Status: EG**Producing Well**

Comment: PR - IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 1" water/oil dump line from separator to tank. 1 – 1" well blow down line from separator to tank. 1-1" water/oil dump line from separator to tank battery.

Corrective Action:

Date:

**Flowline**

#1 Type: Well Site

of Lines

Flowline DescriptionFlowline Type: Well Site

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 1" water/oil dump line from separator to tank. 1 – 1" well blow down line from separator to tank. 1-1" water/oil dump line from separator to tank battery.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment: IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 1" water/oil dump line from separator to tank. 1 – 1" well blow down line from separator to tank. 1-1" water/oil dump line from separator to tank battery.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT