

Inspection Photos

Location Number: 320353



Photo 1 Wellhead from west



Photo 2 Flood anchoring on produced water tank (typical)

Inspection Photos



Photo 3 Produced water tank from west



Photo 4 Crude oil tank from west

Inspection Photos



Photo 5 Separator from east