

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/23/2017

Document Number:

680302062

FIELD INSPECTION FORM

Loc ID 313979 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10203
Name of Operator: BLACK RAVEN ENERGY INC
Address: 165 S UNION BLVD SUITE 410
City: LAKEWOOD State: CO Zip: 80228

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Wehrer, Gene		gwehrer@enerjexresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227414	WELL	TA	05/03/1990	ERIW	087-60019	ADENA J SAND UNIT W-13	SI

General Comment:

[UIC Routine Inspection](#) [UIC MIT performed on 4/21/2017](#) [No UIC Routine Inspections required same year as UIC MIT](#)

Location

Lease Road:			
Type	Access		
comment:	Satisfactory		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Other	# 0			
Comment:	No change in equipment inventoried			
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 227414 Type: WELL API Number: 087-60019 Status: TA Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND
 TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 01/06/2012
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: UIC MIT performed on 4/21/2017 Doc# 680301880

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: UIC Routine

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Continue BMP's](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT