



**photo 1:** Facing west toward the location. There does not appear to have been adequate crop growth at the location.



**photo 2:** Facing north toward the location.