

Inspection Photos

6/23/2017

Operator: CORAL PRODUCTION CORP - 20275

Location ID: 317368

Inspection Doc. Number: 682502334

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: CORAL PRODUCTION CORP - 20275
Location ID: 317368



Photo 1: Photo taken from tank battery location, facing north. Photo shows vegetation over the interim reclamation area.



Photo 2: Photo taken from tank battery location, facing south. Photo shows vegetation over the interim reclamation area.

Inspection Photos
Operator: CORAL PRODUCTION CORP - 20275
Location ID: 317368



Photo 3: Photo of the reference area.



Photo 4: Photo taken from the interim area north of the well, facing east. Photo shows vegetation over the interim reclamation area.

Inspection Photos
Operator: CORAL PRODUCTION CORP - 20275
Location ID: 317368



Photo 5: Photo taken from the interim area northwest of the well, facing west. Photo shows vegetation over the interim reclamation area.



Photo 6: Photo taken from the interim area northwest of the well, facing west. Photo shows vegetation over the interim reclamation area, and the reference area (left of line).