



Photo 1: View of wellhead marker facing northward.



**Photo 2: View of wellhead marker facing southward.
Revegetation is largely comprised of smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*).**



Photo 3: View of wellhead marker facing eastward.



Photo 4: View of wellhead marker facing westward. What appears to be surface owner storage area is in the northwestern corner of the project area.



Photo 5: View of historic pit area that was converted to livestock watering area.