

Flowline and Final Reclamation Inspection

June 27, 2017

Operator: PDC ENERGY INC - 69175

API: 05-123-10803

Weld County, CO

SESE Section 34 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON, PATRICK #1
API: 05-123-10803



Photo 1. Photo taken from the entrance of the southern battery location, facing North. Battery location is not reflective of reference area vegetative conditions.



Photo 2. Photo taken from the entrance of the northern battery location, facing South. Battery location is not reflective of reference area vegetative conditions.

Inspection Photos
Location Name: ANDERSON, PATRICK #1
API: 05-123-10803



Photo 3. Photo taken from the entrance of the location, facing South. Culvert remains and needs to be removed per Rule 1004.