

# Inspection Photos

## Location Number: 440858



**Photo 1 Rig Signage at County Road 21  
from east**



**Photo 2 Track pad at entrance from east**



# Inspection Photos



**Photo 5 Chemical storage in covered conex with curtain wall on south side of drilling pad from the north**



**Photo 6 Interior sound suppression panel next to generators from west**