

# Inspection Photos

6/23/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 331152

Inspection Doc. Number: 682502340

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 331152



**Photo 1:** Photo taken from the well location, facing west. Photo shows all equipment has been removed, location has been returned to cropland. A follow up inspection will need to be conducted in a future growing season to evaluate compliance with reclamation standards.



**Photo 2:** Photo taken from the well location, facing northeast. Photo shows access road remains visible.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 331152



**Photo 3:** Photo taken from the north end of the battery location, facing southeast. Photo shows battery location has not been sufficiently reclaimed.



**Photo 4:** Photo taken from the battery location. Photo shows sign at meter shed still remaining at battery location. .

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 331152



**Photo 5:** Photo taken from the battery location, facing west. Photo shows meter shed still remaining at battery location.