

# Inspection Photos

6/23/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 322764

Inspection Doc. Number: 682502342

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 322764



**Photo 1:** Photo taken from the well location, facing north. Photo shows vegetation over the reclamation area.