

**Inspection Photos**  
**Location Name: LEWTON F UNIT #1**  
**API: 05-001-08920**



**WELLHEAD LEWTON F UNIT #1 NO  
BRADENHEAD PLUMBED UP**



**NO CAP ON PROD OIL TANK VALVE**