

Inspection Photos
Location Name: LEWTON F UNIT #1
API: 05-001-08920



**WELLHEAD LEWTON F UNIT #1 NO
BRADENHEAD PLUMBED UP**

**RISER BY SEPERATOR WHAT IS IT FOR? NEEDS TO BE
MARKED AND TAGGED NTO INSPECTIONS**

