

# Flowline and Final Reclamation Inspection

June 28, 2017

Operator: BARRETT CORPORATION\* BILL - 10071

API: 05-123-12684

Weld County, CO

SESW Section 9 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: LOVELY #1  
API: 05-123-12684



**Photo 1.** Google Earth aerial photo taken 6/26/2006 illustrating the battery location, access road, and well location. Well location appears to pass reclamation but a culvert remains. Battery location has not been reclaimed with several culverts but some of which may be needed because the main access road appears to be used to access a pivot irrigation field to the north.

Inspection Photos  
Location Name: A&N FARMS #1  
API: 05-123-12509



**Photo 2.** Photo taken from the western battery location, facing East. Battery location has not been reclaimed per Rule 1004.



**Photo 3.** Photo taken from the western entrance of the battery location where a culvert remains, facing East. Other culverts are still in place but may need to remain for an access point to a road that appears to be used by the surface owner. Refer to the Photo 1.

Inspection Photos  
Location Name: A&N FARMS #1  
API: 05-123-12509



**Photo 4.** Photo taken from the approximate well location, facing North. Well location and the portion of the access road that traveled west off the main access road appears representative of reference areas, except for a 10' x 10' area.



**Photo 5.** Photo taken from the point where the access road that traveled west to the well location off the main access road intersects. Culvert remains and area has not been regraded or contoured per Rule 1004.