



**photo 1:** Facing west toward the location. The vegetation is predominately Cheat grass at the location. The surrounding vegetation is Crested wheat grass.



**photo 2:** There are degraded wooden boards that remain.





**photo 3:** Facing east at the location. The vegetation has not adequately established at this area.



**photo 4:** Facing south toward the location. The surrounding vegetation is comprised of Crested wheat grass.