

Photo#1:

View over Location Center to East.



June 17, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Biasi Bruno PA Woosley#2 API#077-40370