

# Inspection Photos

6/30/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323052

Inspection Doc. Number: 682502370

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323052



**Photo 1:** Photo taken from the well location, facing west. Photo shows perennial crop has not been able to re-establish. Additional reclamation required.



**Photo 2:** Photo taken from the well location, facing north. Photo shows access road loop leading to well has not been reclaimed and returned to crop.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323052



**Photo 3:** Photo taken from the east end of the battery location, facing east. Photo shows Musk thistle on location. This is a Colorado State listed noxious weed and needs to be managed.



**Photo 4:** Photo taken from the battery, facing west. Photo shows erosion occurring on location.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323052



**Photo 5:** Photo taken from the access road, facing east. Photo shows Musk thistle on access road. Musk and Canada thistle found throughout access road. These area Colorado State listed noxious weeds and need to be removed.



**Photo 6:** Photo taken from the access road, facing west. Photo shows Canada thistle on access road. Musk and Canada thistle found throughout access road. These area Colorado State listed noxious weeds and need to be removed.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323052



**Photo 7:** Photo taken from where access road meets the county road. Photo shows Noble sign at access road entrance.