

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

						corrective date
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:					Date:	
Type: Gas Meter Run	# 1					
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment	# 1					
Comment:	Wellhead					
Corrective Action:					Date:	
Type: Vertical Separator	# 1					
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 284262 Type: WELL API Number: 071-08762 Status: TA Insp. Status: TA

Producing Well

Comment: PR

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Passed MiT on (10/27/14).

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Passed MiT on (10/27/14).	duranj	06/30/2017