

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Deadman # & Marked	# 3				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			
Type: Ancillary equipment	# 1				
Comment: Wellhead					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259976 Type: WELL API Number: 071-07334 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: 30' x 70'

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	262419	852627	

COGCC Comments

Comment	User	Date
Passed MIT on (09/08/14).	duranj	06/30/2017