



**photo 1:** Facing north toward the access road.



**photo 2:** Facing west toward the location. There are areas where desirable vegetation has not established.





**photo 3:** Facing east toward the location.



**photo 4:** Facing northwest toward the surrounding pasture.