



Photo 1: View of risers on well pad at 37.61975, -108.97356.



Photo 2: View of more risers on the well pad at 37.61988, -108.97350.



Photo 3: View of risers on well pad at 37.62005, -108.9733.



Photo 4: View of riser at access road entrance at 37.61740, -108.9762.



Photo 5: View of riser across the County Road from the access entrance at 37.61751, -108.97640.



Photo 6: View of area on well pad that with little vegetation.



Photo 7: View of salt cedar (*Tamarix* sp.) growing on the well pad. This is a noxious weed and needs to be removed.



Photo 8: View of jointed goatgrass growing in the well pad area. This is a noxious weed species that needs to be controlled.



Photo 9: View of old well sign still present.



Photo 10: View of rock fill still in place. Location not recontoured.