



Photo 1: View of the project area from southwestern edge facing center. Vegetation within the project area does not appear to meet the 80 percent vegetation threshold. A future vegetation assessment will be conducted.



Photo 2: View of the western edge of the project area from the access road facing northward. A line between the well pad and access road, and surrounding cropland is still visible.