

# Inspection Photos

7/3/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 330632

Inspection Doc. Number: 682502373

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 330632



**Photo 1:** Photo taken from the southeast corner of the battery location, facing southeast. Inspection doc. # 682401398 required operator to remove risers from battery location. Photo shows risers have not been removed.