

Inspection Photos

7/3/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 682502377

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329551



Photo 1: Photo taken from the battery location southeast of the well, facing south. Photo show meter shed remains on location.



Photo 2: Photo taken from the battery location southeast of the well, facing north. Photo shows battery location remains bare and exposed soil. Battery requires stabilization.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329551




Photo 3: Photo taken from the door of the meter shed. Writing indicates meter was related to the "Riter C 18-10".



Photo 4: Photo taken from the well location, facing northeast. Photo shows vegetation over the reclamation area has not achieved a uniform cover and does not appear to be progressing to 80% cover to that of the reference.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329551



Photo 5: Photo taken from the well location, facing east. Photo shows vegetation over the reclamation area has not achieved a uniform cover and does not appear to be progressing to 80% cover to that of the reference.



Photo 6: Photo taken from the adjacent reference area. Reference area is a irrigated hay meadow composed predominantly of perennial grass.