

# Inspection Photos

7/3/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327399

Inspection Doc. Number: 682502381

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327399



**Photo 1:** Photo taken from the battery location, facing northwest. Battery location has had facilities removed (except meter shed), however no other reclamation work appears to have been conducted



**Photo 2:** Photo taken from the battery location, facing west. Battery location has had facilities removed (except meter shed), however no other reclamation work appears to have been conducted

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327399



**Photo 3:** Photo taken from the battery location, facing southwest. Battery location has had facilities removed (except meter shed), however no other reclamation work appears to have been conducted .



**Photo 4:** Photo taken from the battery location. Photo shows meter shed remaining on location. "Freedom Two C" was written on the inside of the door.



Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327399



**Photo 5:** Photo taken from the well location facing west. Photo shows well does not appear to reflect the adjacent reference area (see photo 7 ), and remains unvegetated in areas, or with weedy undesirable plant species establishing.



**Photo 6:** Photo taken from the well location facing northwest. Photo shows well does not appear to reflect the adjacent reference area (see photo 7), and remains unvegetated in areas, or with weedy undesirable plant species establishing.




Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327399



**Photo 7:** Photo of the vegetation on the adjacent reference area.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327399



**Photo 8:** 2010 aerial imagery. Photo shows perimeter of the Freedom Two C tank battery, as indicated with the yellow polygon.



Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327399



**Photo 9:** Current aerial imagery (2016). Photo shows that an additional tank battery facility (Broomfield battery) has been constructed, and that little reclamation work appears to have been conducted at the Freedom battery.